



NOTES;
1. MANIFOLD MUST BE LEAK TESTED AFTER WELDING OPERATIONS.
MANIFOLD MUST BE 100 % LEAK FREE